

UNCLASSIFIED

AD NUMBER	
AD361297	
CLASSIFICATION CHANGES	
TO:	unclassified
FROM:	restricted
LIMITATION CHANGES	
TO:	Approved for public release, distribution unlimited
FROM:	Controlling Organization: British Embassy, 3100 Massachusetts Avenue, NW, Washington, DC 20008.
AUTHORITY	
DSTL, ADM 227/2621, 18 Nov 2008; DSTL, ADM 227/2621, 18 Nov 2008	

THIS PAGE IS UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

NOTICE:

THIS DOCUMENT CONTAINS INFORMATION
AFFECTING THE NATIONAL DEFENSE OF
THE UNITED STATES WITHIN THE MEAN-
ING OF THE ESPIONAGE LAWS, TITLE 18,
U.S.C., SECTIONS 793 and 794. THE
TRANSMISSION OR THE REVELATION OF
ITS CONTENTS IN ANY MANNER TO AN
UNAUTHORIZED PERSON IS PROHIBITED
BY LAW.

U.S. CONFIDENTIAL-Modified Handling Authorized

U.K. RESTRICTED

EXCLUDED FROM AUTOMATIC REGRADING: DOD DIR 5200.10

DOES NOT APPLY

NSIC/01197/65

Report No. 2433/3206/29
Date 24 MAR 1965

ELECTRICAL DEPARTMENT

ADMIRALTY ENGINEERING
LABORATORY

WEST DRAYTON, MIDDLESEX

CATALOGED BY: DDC

AS AD NO 361297

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINER
MADE BY PERIALI LTD. AND UNITED EBONITE & LORIVAL LTD.
FOR SUBMARINE CELL TYPE 8000 - SHOCK.

U

3 6 1 2 9 7



U.S. CONFIDENTIAL-Modified Handling Authorized

U.K. RESTRICTED

EXCLUDED FROM AUTOMATIC REGRADING: DOD DIR 5200.10

DOES NOT APPLY

Copy No. 2

RESTRICTED

RESTRICTED

U. S. CONFIDENTIAL

This document is the property of Her Majesty's Government. It is for the information of officers and responsible officials. The officer or official in possession of this document will be responsible for its safe custody and for ensuring that its contents are not disclosed to any unauthorised person.

REPORT NO. 2433/3206/29

DATE 24 Nov 1965

This document must be kept under lock and key when not in actual use. Any loss or destruction must be reported immediately to the issuing authority through the normal channels.

ELECTRICAL DEPARTMENT,
ADMIRALTY ENGINEERING LABORATORY,
WEST DRAYTON, MIDDLESEX.

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS
MADE BY PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR
SUBMARINE CELL TYPE 8000 - SHOCK.

Investigator:-

R.J.L. Lewery

"This document contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U. S. C., Section 793 and 794. Its transmission or the revelation of its contents in any manner to an unauthorized person is prohibited by law."

Head of Section

Authorised

Head of Electrical Department
A.E.L.

CT.

U. S. CONFIDENTIAL
MODIFIED HANDLING AUTHORIZED
RESTRICTED

RESTRICTED

SUMMARY

Two experimental thin-panneled homogeneous glass-fibre/resin containers for cell Type 8000 were subjected to shock tests. The shock resistance of the container made by United Ebonite & Lorival Ltd., was satisfactory but the centre vertical rib of one long side of the container made by Permali Ltd., fractured and was separated from the side. Both containers bulged considerably.

RESTRICTED

RESTRICTED
U.S. CONFIDENTIAL
MODIFIED HANDLING AUTHORIZED

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY
PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR
SUBMARINE CELL TYPE 8000 - SHOCK.

1. INTRODUCTION

Report No. 2430/3206/25 described an investigation carried out to determine the shock resistance of two experimental thin-panelled homogeneous glass-fibre/resin containers made by Permal Ltd. for submarine cell Type 6560. The containers, which were considerably lighter than the Cat. No. X266 Mk2 container, were similar in all respects except that the glass-fibre fabric covering the inner and outer surfaces of one was Hook Lone and of the other the t-rill used for containers Cat. No. X266 Mk2. The shock resistance of both containers was satisfactory but the bulge was greater than could be accepted.

Two further containers of this type were made for cell Type 8000 and in these the horizontal strengthening ribs were resited and of a different shape, and in addition a rib was incorporated along the vertical centre line of each long side. This report describes the investigation carried out at the Laboratory in May and June 1961 to determine their shock resistance and bulge.

2. PARTICULARS OF CONTAINERS

The containers were marked Permal 8000 and U.E.L. 8000. Their measurements and weights were as follows:-

TABLE 1

Manufacturer		Permal	U.E.L.
Exterior	Height in.	39 $\frac{5}{8}$	39 9/16
	Length "	21 1/16	21 1/16
	Width "	13 13/32	13 $\frac{5}{8}$
Interior	Height "	38 11/16	38 11/16
	Length "	20 3/32	20 3/32
	Width "	12 $\frac{1}{4}$	12 $\frac{1}{4}$
Average thickness of upper panels at centre (in.)		0.103	0.107
Weight (without lining) (lb)		45	43 $\frac{1}{2}$

3. EXAMINATION BEFORE SHOCK TEST

(a) To enable the bulge of the container to be measured and the location of any damage to be given the parts of the container were marked and described as shown in Fig. 1.

(b) The exterior and interior of the containers were examined on receipt and the following damage and imperfections were observed.

Permal Container

(i) Damage:- Small piece of resin dislodged from bottom edge of one base pad.

(ii) Imperfections. Exterior:- Narrow areas of resin slightly or moderately opaque at following positions:- Below junction of base and side AB from corner rib A to near lifting channel; along boundaries BC1 od CD3L da, CD2R od, CD3R od, and DA3 od; small areas at corners BC 3c and d, CD1Ro, CD3Rb and DA1d.

U.S. CONFIDENTIAL
RESTRICTED HANDLING AUTHORIZED
Interior

- 2 -

Interior:- Narrow areas of resin slightly or moderately opaque at following positions. Along boundaries AB2Lcd, 1Rab, 1R bed 2Rbe; BC1cd, 2cd, 2 ab, 3 cda; CD2L cda, 3Lcd, 2Rabed, 3Rda, 1Rbe; DA2 cd and 3 cd. At corners AB1Lb, 2Lb, 3La, 1Rb, 1Ro, 2 Ra, 3Ra, 1Ro; CD3Ra and b.

U.E.L. Container

(i) No damage.

(ii) Imperfections. Exterior:- Many resin-rich areas on chamfers of vertical and horizontal ribs and at junction of base and sides.

Interior:- Resin rich along base fillet of side CD and over a few areas near the top of sides AB and CD.

4. MEASUREMENT OF BULGE

Measurements were taken with the container empty between opposite points on the exterior vertical centre lines of the long sides at distances of 1, 5, 8, 16, 24, 28, 32, and 35½ in. from the top edge, and were repeated after assembling the container as a cell before the shock test, after the 4 ft 6 in. blow with the cell assembled, and after removing the plate group, liquid and rubber lining for the final examination. The differences between the first and subsequent measurements are given in Table 2.

5. SHOCK TEST

The containers were assembled as cells with elements Type 8000 and covers Cat. No. X283 and filled to the correct level with water. They were then placed in turn on a solid teak baseboard 1½ in. thick and mounted on the upward blow shock machine. A series of blows was applied to each cell commencing at a height of 2 ft 6 in. and increasing by 6 in. steps to 4 ft 6 in. The exterior of the container was examined after each blow and the interior after the 2 ft 6 in., 3 ft 6 in. and 4 ft 6 in. blows. The results of the shock test are given in Tables 3 and 4.

6. DISCUSSION OF RESULTS

(a) Pernali Container

(i) Damage due to shock:- The outer glass-fibre fabric covering of the bottom section of the centre vertical rib of both sides terminated at the lower chamfer of No. 2 horizontal rib. On side AB the resin at this boundary was cracked by the 2 ft 6 in. blow and on side CD a few hairline cracks appeared between corners 2Lc and 2Ra, i.e. about 1½ in. above the boundary of the cloth. There was also an increase in the capacity of the exterior and interior resin along many of the boundaries between panels and ribs (where the cross section of the material changed sharply) and a wall in the outer cloth along two of the boundaries. This damage was increased by subsequent blows and after the 4 ft 6 in. blow the bottom section of the centre vertical rib of side AB (see Fig. 3(a) and 4(b)) was fractured and separated from the body of the container over 1/3 rd of its length and the damaged outer and inner skins at the boundaries of several panels could be cut easily and removed from the container. The

RESTRICTED

- 3 -

resin beneath these damaged areas was white and powdery and could be scraped easily from the glass fibres. When the container was subsequently half filled with water and tested for leakage a seepage of 10 ml in 1 hour occurred, mostly through the damaged resin along the lower boundaries of the bottom panels. Figs. 3(b), 4(a) and 5(a).

(ii) Bulge between the long sides. The maximum bulge before the shock test was 0.274 in. between points 16 in. from the top of the container. The maximum bulge after the shock test was 0.304 in. between points 32 in. from the top of the container. The maximum permanent set 2 hours after the last blow was 0.154 in. between points 32 in. from the top of the container.

(b) U.E.L. Container

(i) Damage due to shock. The damage to this container up to the final blow was slight and comprised very faint crazing of the bottom and middle panels, cracks in the resin-rich areas of No. 2 rib of all sides, hairline cracks along the base fillets of all sides, an increase in the opacity of the resin along these areas that were slightly opaque before the shock test and two short wales (both less than 0.005 in. high) on the interior surface. After the final blow there was an increase in the intensity and extent of the crazing, and in the number and depth of the cracks in the resin along the interior base fillets. Along interior base fillet CD, where the fabric covering the side and base did not cross the fillet, the resin was chipped away in two places to a depth of about $\frac{1}{8}$ in. before reaching the sub-surface layer of glass fabric. Subsequent to this examination the container was tested for leakage and it was observed that about $\frac{1}{3}$ rd of the total leakage of 6 ml in one hour occurred in places, along the junction of side CD and the base. It is probably therefore that the cracks did extend through the glass material, although this was not apparent from the visual examination.

(ii) Bulge between the long sides:- The maximum bulge before the shock test was 0.300 in between points 16 in. from the top of the container. The maximum bulge after the shock test was 0.262 between points 28 in. from the top of the container. The maximum permanent set was 0.104 in. at points 32 in. from the top of the container.

CONCLUSIONS

The experimental thin-panelled homogeneous glass-fibre/resin container made by United Ebonite & Lorival Ltd. for cell Type 8000 had a satisfactory resistance to shock and was only slightly damaged by the shock test. The shock resistance of the container made by Permali Ltd., to the same design was not satisfactory in that the centre vertical rib of one long side was fractured and separated from the side. Both containers bulged considerably and it is possible that the bulge might be excessive at higher temperatures.

RESTRICTED

TABLE 2

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY PERALI LTD. AND UNITED FRONTIER & LORIVAL LTD. FOR CELL TYPE 8000 - SHOCK.

Bulge between long sides of container at 18° to 21° C

Stage of Test	Make of container	Distance from top of container (in.)									
		1	5	8	16	20	24	28	32	35½	
					Total bulge (in.)						
Cell assembled before shock test.	Pernali U.E.L.	0.081 0.074	0.167 0.163	0.227 0.226	0.274 0.300	0.268 0.289	0.254 0.280	0.215 0.231	0.141 0.141	0.054 0.057	
Cell assembled after shock test.	Pernali U.E.L.	0.038 0.064	0.102 0.101	0.152 0.130	0.209 0.167	0.218 0.189	0.242 0.243	0.249 0.262	0.304 0.230	0.124 0.135	
Container emptied for final examination.	Pernali U.E.L.	0.002 -0.003	-0.010 -0.008	-0.018 -0.008	-0.015 -0.016	-0.007 0.009	-0.013 0.045	0.049 0.081	0.154 0.104	0.066 0.073	

Report No. 2433/3206/29

**EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY PERMA
LONIVAL LTD. FOR SUBMARINE CELL TYPE 80A**

Results of Shear Test on Container made by 1

Blow		Damage	Remarks
No.	Height		
1	2 ft 6 in.	Exterior Interior	Centre vertical rib (c.v.r.) of side AB cracked at junction with horizontal hairline cracks in resin pool across c.v.r. of side CD just above rib 2. boundaries of the panels as follows:- AB1Rod opaque area 9 in. x $\frac{1}{8}$ in. x $\frac{1}{8}$ in; corner CD1Ro opaque 1 in. ² ; boundary DA1cd - opaque area 4 in. Increase in opacity of resin and damage to bond between inner cloth and 1/16 in. high; BC2ab - wale 10 in. x $\frac{1}{8}$ in. x 0.001; BC3cd wale 10 in. 8 in. x $\frac{1}{8}$ in. x 0.005 in. high; CD2Rad - wale 8 in. x $\frac{1}{8}$ in. x 0.01 in. 8 in. x $\frac{1}{8}$ in. x 0.007 in. high.
2	3 ft	Exterior	Fracture of resin of c.v.r. below rib AB2 to beneath first layer of cloth additional cracks in surface resin above rib CD2. wale 1 in. x $\frac{1}{8}$ in. DA3c.
3	3 ft 6 in.	Exterior Interior	Probable fracture of c.v.r. of side AB to level of panel. Damage to fillet along middle 4 in. of boundary BC1cd, threads at outer cloth white and and 1 BC2 cd - opaque area 4 in. x $\frac{1}{8}$ in; BC1cd - ridge 1/16 in. wide in ruptured at junction of panel and chamfer of rib. CD - diagonal cracks and a wale 1/32 in. high in corner 1Ro. Strands of outer cloth at DA1d Many additional hairline cracks along base fillet AB and in adjacent resin along boundaries of panels as follows:- $\frac{1}{8}$ in. wide band of opaque resin high along AB2Lab and 7 in. x $\frac{1}{8}$ in. x 0.005 in. high along AB2Lbc. Blis to 8 $\frac{1}{2}$ in. x $\frac{1}{8}$ in. x 0.01 in. high. Height of wale at DA1cd increased to
4	4 ft	Exterior	Small piece of resin dislodged from boundary of fractured c.v.r. and di fracture indicating separation of lower part from body. Wale about 1/6 along AB2R and 3Rab. Wale along DA1cd now 3/64 in. high; wale 7 in. x corner C. A few additional hairline cracks in chamfers of rib CD2.
5	4 ft 6 in.	Exterior Interior	Centre vertical rib separated from container between 5 in. and 8 in. from 3(a) and 4(b)). About 20 strands of fibres pulled from surface resin; AB3Rod; Additional damage to glass-fibre/resin along boundaries of panels small area of opaque resin in corner BC3c; a few additional hairline cracks of the resin between the cracks; height of ridge along CD1Rod increases fibres loose and a few fibres ruptured in the wale along DA1cd (Fig. 5) cracks in resin between cover-securing screw holes Nos. 1, 2, and 5 and Interior A few additional hairline cracks in base fillets AB (Fig. 5(c)) BC and CD panels as follows:- Height of wale at AB1Rod, increased to 0.007 in.; white in colour and now about 1/16, 1/32 and 1/64 in. high respectively CD2L, 2R, 3L and 3Rac slightly increased in height but all less than 0.01 wale DA3c to 1/32 in. high (Fig. 5(b)). The glass-fibre/resin beneath

Note 1. The exterior sides panels and ribs of the containers were marked as shown in Fig. damage to a particular part of the container could be located either on the exterior

Note 2. The wales along the boundaries of the panels were cut in several places to inspect resin was white and powdery and the glass fibres could be scraped easily

1
RESTRICTED

RESTRICTED

TABLE 3

THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY PERMALI LTD AND UNITED EBONITE & LORIVAL LTD. FOR SUBMARINE GULL TYPE 8000 - SHOCK.

Results of Shock Test on Container made by Permal Limited.

Remarks

rib (c.v.r.) of side AB cracked at junction with horizontal rib 2 and several hairline cracks below. Chain of short resin pool across c.v.r. of side CD just above rib 2. Resin opaque and strands of outer cloth slightly raised along the panels as follows:- AB1Red opaque area 9 in. x $\frac{1}{8}$ in.; BC1od - wale 7 in. long $\frac{1}{64}$ in. high; BC2od - opaque area 2 $\frac{1}{2}$ in. D1Re opaque 1 in. $\frac{1}{2}$; boundary DA1od - opaque area 4 in. x $\frac{1}{8}$ in. and wale about $\frac{1}{64}$ in. high.

ty of resin and damage to bond between inner cloth and glass-fibre/resin beneath as follows:- BC1ab - wale 4 in. x $\frac{1}{8}$ in. x C2ab - wale 10 in. x $\frac{1}{8}$ in. x 0.001; BC3od wale 10 in. x $\frac{1}{8}$ in. x 0.005 in. high; CD2Lab and 2Rab - 2 wale each .005 in. high; CD2Rad - wale 8 in. x $\frac{1}{8}$ in. x 0.01 in. high; CD3Lad, wale 9 in. x $\frac{1}{8}$ in. x 0.005 in. high; CD3Rad, wale 07 in. high.

of c.v.r. below rib AB2 to beneath first layer of cloth; a number of additional hairline cracks above fracture, two in surface resin above rib CD2. wale 11 in. x $\frac{1}{8}$ in. x $\frac{3}{32}$ in. high at CD1Re; Small areas of opaque resin at CD1Re and

of c.v.r. of side AB to level of panel. Damage to fibre-glass/resin as follows:- AB1Lod increase in opacity of resin of boundary BC1od, threads of outer cloth white and above level of resin; small areas of opaque resin at corners BC1c and 7 in. x $\frac{1}{8}$ in.; BC1od - ridge $\frac{1}{16}$ in. wide in an 8 in. x $\frac{1}{8}$ in. band of opaque resin; numerous glass fibres in of panel and chamfer of rib. CD - diagonal cracks in surface resin across corners 1Lb and 1Ra of chamfers of c.v.r. n. high in corner 1Re. Strands of outer cloth at DA1d whiter and slightly proud of surface.

airline cracks along base fillet AB and in adjacent resin pools on surface of base. Additional damage to glass-fibre/resin of panels as follows:- $\frac{1}{4}$ in. wide band of opaque resin along middle 3 in. of AB1L and 1Red; wale 5 in. x $\frac{1}{16}$ in. x 0.005 in. and 7 in. x $\frac{1}{8}$ in. x 0.005 in. high along AB2Lbe. Blister $\frac{1}{4}$ in. x 0.01 in. high at AB3Lc; wale at BC3od increased x 0.01 in. high. Height of wale at DA1od increased to $\frac{1}{32}$ in.

sin dislodged from boundary of fractured c.v.r. and difference of level of $\frac{3}{64}$ in. between parts of rib on either side of ng separation of lower part from body. Wale about $\frac{1}{64}$ in. high along AB3Red and a 4 in. x $\frac{1}{8}$ in. area of opaque resin ab. Wale along DA1od now $\frac{3}{64}$ in. high; wale 7 in. x $\frac{1}{8}$ in. x 0.005 in. high along CD1Red with a few hairline cracks at additional hairline cracks in chamfers of rib CD2.

lb separated from container between 5 in. and 8 in. from base and outer cloth delaminated at AB1Lb, and AB1Ra (Fig. About 20 strands of fibres pulled from surface resin along AB1Red. Several strands of fibres ruptured in wale along al damage to glass-fibre/resin along boundaries of panels as follows:- Wale along BC1od now $\frac{1}{16}$ in. high (Fig. 3(b)) que resin in corner BC3c; a few additional hairline cracks in c.v.r., between corners AB2Lc and AB2Rd and some granulation seen the cracks; height of ridge along CD1Red increased to $\frac{1}{64}$ in. and cracks along peak (Fig. 4(a)) several strands of a few fibres ruptured in the wale along DA1od (Fig. 5(a)), (See note 2). Short vertical between cover-securing screw holes Nos. 1, 2, and 5 and interior.

airline cracks in base fillets AB (Fig. 5(c)) BC and CD. Additional damage to glass-fibre/resin along boundaries of :- Height of wale at AB1Red, increased to 0.007 in.; surface resin cracked just below AB3Red; wales BC1, 2 and 3od nd now about $\frac{1}{16}$, $\frac{1}{32}$ and $\frac{1}{64}$ in. high respectively; a number of cracks along BC3od; wales along boundaries 3Rac slightly increased in height but all less than 0.010 in. high. Height of wale DA1od increased to $\frac{1}{16}$ in. high and 2 in. high (Fig. 5(b)). The glass-fibre/resin beneath all the wales was probably damaged (See Note 2).

nd ribs of the containers were marked as shown in Fig. 1 and were carried through to the interior so that of the container could be located either on the exterior or interior surface by the same group marking.

les of the panels were cut in several places to inspect the glass-fibre/resin below: in all cases the and the glass fibres could be scraped easily from the resin.

2

RESTRICTED

Report No. 2433/3206/29

**EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY FERMAL LTD., AND
LCRYVAL LTD. FOR SUBMARINE CELL TYPE 2000 - SHOCK**

Results of Shock Test on Container made by United Ebonite & Co.

Blow		Damage	Remarks
No.	Height		
1	2 ft 6 in.	Exterior	Areas of faint crazing on panels AB and CD 1L and 1R, BC1, and on base bc. A number of hairline cracks across chamfers of rib AB2 and a few across 1
		Interior	A few hairline cracks in resin-rich fillets between base and sides AB, BC boundaries AB1L and 1R ab and cd.
2	3 ft	Exterior	Slight increase in intensity of crazing lines in panels AB and CD 1L and 2L and 2R. A few additional hairline cracks across chamfers AB, 1
3	3 ft 6 in.	Exterior	Slight increase in intensity of crazing lines in the base and in panels A of hairline cracks across chamfers AB and CD 1Lbc and 1Rcd and across cha Short vertical cracks in resin between cover-securing screw holes Nov. 5
		Interior	Number of additional hairline cracks in resin along fillet between base and other base fillets. Short seal less than 0.005 in. high along boundaries
4	4 ft	Exterior	Many additional crazing lines in bottom panels of all sides and a few in hairline cracks across chamfers CD1L and 1R ab and a few in bottom part of in opacity of resin along short length of chamfer AB3Rda.
5	4 ft 6 in.	Exterior	Increase in intensity of crazing lines in panels AB and CD1L, 2L, 2R and new areas of crazing in top panels of sides AB and CD. Few additional ha AB and CD1L bc and 1Rda, and in resin-rich areas along rib CD and DA1. A sides and centre pad.
		Interior	Increase in opacity of small areas of resin and a number of additional ha BC and CD; along base fillet CD many of these cracks extended to the sub places, the resin forming the fillet was delaminated over small areas (see resin dislodged from base fillet BC. A few hairline cracks along vertical

Note 1. The resin along fillet CD was removed in three places until glass-fibre material and 5/32 in. No ruptured glass fibres were observed or granulation of the resin; it is probable that some of these cracks extended beyond this glass-fibre material.

1

RES

RESTRICTED

TABLE 4.

PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY PERMALI LTD., AND UNITED EBONITE & LORIVAL LTD. FOR SUBMARINE CELL TYPE 8000 - SHOCK

Results of Shock Test on Container made by United Ebonite & Lorival Ltd.

Remarks

faint crazing on panels AB and CD 1L and 1R, BC1, and on base between short sides and centre pad. (See Note 1 Table 3.)
of hairline cracks across chamfers of rib AB2 and a few across the chamfers of ribs BC2 and CD2.

hairline cracks in resin-rich fillets between base and sides AB, BC and CD. Slight increase in opacity of resin along
sides AB1L and 1Rab and cd.

increase in intensity of crazing lines in panels AB and CD 1L and 1R and new areas of faint crazing lines on panels AB
2L and 2R. A few additional hairline cracks across chamfers AB, BC and CD2.

increase in intensity of crazing lines in the base and in panels AB and CD 1L, 2L, 2R and 3L, and panel BC1. A number
of cracks across chamfers AB and CD 1Lbc and 1Rcd and across chamfers of No. 2 rib of all sides.
vertical cracks in resin between cover-securing screw holes Nos. 5 and 6 and interior.

few additional hairline cracks in resin along fillet between base and side CD and a few additional hairline cracks in
base fillets. Short well less than 0.005 in. high along boundaries CD 2Lab and CD3Lcd.

additional crazing lines in bottom panels of all sides and a few in panels AB and CD 2L and 3L. Numerous additional
cracks across chamfers CD1L and 1R ab and a few in bottom part of centre vertical rib (c.v.r.) of side AB. Increase
in opacity of resin along short length of chamfer AB3Rda.

increase in intensity of crazing lines in panels AB and CD 1L, 2L, 2R and 3L (for view of worst area of crazing see Fig. 2a) and
of crazing in top panels of sides AB and CD. Few additional hairline cracks in No. 2 ribs of all sides, in chamfers
D1L bc and 1Rda, and in resin-rich areas along rib CD and DA1. A few additional crazing lines on base between short
and centre pad.

increase in opacity of small areas of resin and a number of additional hairline cracks along fillets between base and sides AB,
D; along base fillet CD many of these cracks extended to the sub surface layer of glass fabric from which, in several
places the resin forming the fillet was delaminated over small areas (see Fig. 2(b)) (See note 1). A few small flakes of
resin slodged from base fillet BC. A few hairline cracks along vertical fillets A and B.

Fillet CD was removed in three places until glass-fibre material was encountered between depths of 3/32 in.
ruptured glass fibres were observed or granulation of the resin but from the result of the test for leakage
that some of these cracks extended beyond this glass-fibre material.


Report No. 2433/3206/29

RESTRICTED

2

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY FOR SUBMARINE CELL TYPE 8000 - SHOCK.




PARTS OF CONTAINER AND COVER.



RESTRICTED


GLASS-FIBRE/RESIN CONTAINERS MADE BY PERMALI LTD. AND UEL LTD. OR SUBMARINE CELL TYPE 8000 - SHOCK.

PARTS OF CONTAINER AND COVER.



Section through X₂X₂


(c) SECTIONS THROUGH CORNER RIB B.



(c) View of cover marked for measurement of distortion.

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY
PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR CELL
TYPE 8000 - SHOCK.

Views showing damage to U.E.L. Container as a result of
the shock test.




(a) View showing crazing of panel CD1L



(b) View showing cracks and resin-richness of base fillet of side CD.

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY
PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR CELL
TYPE 8000 - SHOCK.

Views showing damage to the Permal container as a result
of the Shock Test.




(a) General view of container.




(b) View showing damage to panel BC1.

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY
PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR CELL
TYPE 8000 - SHOCK.

Views showing damage to the Permali container as a result
of the shock test.



(a) View showing damage to panel CD1R




(b) View showing damage to lower part of centre vertical rib of
side AB at AB1Lb-AB1Ra.

EXPERIMENTAL THIN-PANELLED GLASS-FIBRE/RESIN CONTAINERS MADE BY
PERMALI LTD. AND UNITED EBONITE & LORIVAL LTD. FOR CELL
TYPE 8000 - SHOCK.

Views showing damage to the Permal container as a result of
the shock test.



(a) View showing damage to panel DA1.



(b) View of interior of side DA showing wale above No. 3 rib.



(c) View showing cracks in resin pools, and along fillet between base and
side AB.



Information Centre
Knowledge Services
(dstl) Porton Down,
Salisbury
Wiltshire
SP1 0RJ
22060-6218
Tel: 01980-613753
Fax: 01980-613950

Defense Technical Information Center (DTIC)
8725 John J. Kingman Road, Suit 0944
Fort Belvoir, VA 22060-6218
U.S.A.

AD#: AD361297

Date of Search: 18 November 2008

Record Summary: ADM 227/2621

Title: Experimental thin panelled glass fibre/resin containers for submarine cell type 8000:
shock

Availability Open Document, Open Description, Normal Closure before FOI Act: 30 years

Former reference (Department) 2433/3206/29

Held by The National Archives, Kew

This document is now available at the National Archives, Kew, Surrey, United Kingdom.

DTIC has checked the National Archives Catalogue website (<http://www.nationalarchives.gov.uk>) and found the document is available and releasable to the public.

Access to UK public records is governed by statute, namely the Public Records Act, 1958, and the Public Records Act, 1967.

The document has been released under the 30 year rule.

(The vast majority of records selected for permanent preservation are made available to the public when they are 30 years old. This is commonly referred to as the 30 year rule and was established by the Public Records Act of 1967).

This document may be treated as UNLIMITED.